

2017 Chevrolet Volt

1G1RD6S59HU100179 • 140,218mi

Front Wheel Drive • 1.5L 4 Cylinder Engine • Gas/Elec (18.4 kWh) • A/T • Hard Top • Leather



1.3
AutoGrade
Rough



Condition
Details



No Structural
Damage



Prior Paint



Tires



AutoCheck
Clean



Drivable



Starts



Other Odor



Keys | Fobs
1 | 0



Title? (No
Data)




Announcements

- AS IS

High Value Options

- Adaptive Cruise Control
- Automatic Parking
- Back-Up Camera
- Blind Spot Monitor
- Bluetooth Connection
- Climate Control
- Cross-Traffic Alert
- Heated Front Seat(s)
- Heated Rear Seat(s)
- Heated Steering Wheel
- Keyless Start
- Lane Departure Warning
- Lane Keeping Assist
- Navigation System
- Premium Sound System
- Rear Parking Aid
- Satellite Radio
- Smart Device Integration
- Tire Pressure Monitor
- WiFi Hotspot

Condition Details




























None ● ● ● Severe


● Structural Issue

Exterior (30)






Description	Condition	Status	Image	Additional Info
● Windshield	Cracked			
● Grille Molding	Broken			

Description	Condition	Status	Image	Additional Info
● Front Bumper Cover	Broken			
● Roof	Oxidized			
● Right Drip Rail	Peeling			oxidation
● LF Door	Mult Dents/No Paint Dmg			
● LF Fender	Mult Dents/No Paint Dmg			
● LF Tire	Worn			
● L Qtr Panel	Dent/Paint Dmg			
● L Qtr Panel	Prev Repair			
● LR Door	Mult Dents/Paint Dmg			
● LR Tail Lamp	Broken			
● LR Tire	Worn			
● Rear Bumper Cover	Dent/Paint Dmg			
● Rear Bumper Cover	Prev Repair			
● Deck Lid Emblem	Broken			

Description	Condition	Status	Image	Additional Info
● RR Door	Prev Repair			
● RR Window	Replaced			
● RR Wheel	Curb Rash			
● R Headlight	Broken			
● R Qtr Panel	Heavy Mult Scratches			
● R Qtr Panel	Mult Dents/No Paint Dmg			
● R Qtr Panel	Prev Repair			
● R Rocker Panel Molding	Broken			
● RF Door	Mult Dents/Paint Dmg			
● RF Window	Replaced			
● RF Fender Liner	Broken			
● RF Fender	Severe Damage			
● RF Wheel	Curb Rash			

Description	Condition	Status	Image	Additional Info
● RF Tire	Worn			


Interior (7)

Description	Condition	Status	Image	Additional Info
● Radio Display/Touch Screen	Heavy Mult Scratches			
● Owners manuals	Missing			
● Warranty Books	Missing			
● Warning - Traction Control	On			
● Warning - ABS	On			
● Warning - Engine	On			
● Center Console Trim Panel	Peeling			



Tires & Wheels

Wheels Aluminum



Left Front
Michelin
1/32"
215/50R17

Right Front
Michelin
3/32"
215/50R17

Left Rear
Michelin
2/32"
215/50R17

Right Rear
Michelin
5/32"
215/50R17

Spare
(Compact)
N/A

● 6/32 +
● 5/32 to 4/32
● < 4/32
● N/A

Details

Exterior Color Mosaic Black Metallic 	Interior Color Jet Black/Jet Black Top Type Hard Top MSRP \$40,155	Title State -- Title Received -- Received Date 08/24/2023	Inspection Location Work Order 3657676 In Service Date 04/20/2016	Org Mfg Basic Warranty *3 Years/36,000 Miles *Manheim is not responsible for voided warranties
-----------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------	--------------------------------------------------------------------------	-------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------

EV Information

Current Range --	Battery Health Score --	Charging Cable Not Applicable	Charging Level AC Level 2	Battery Warranty 8 Years/150000 mi
State of Charge --	Connector Type J1772	Battery Capacity 18.4 kWh	EPA Mileage 53 mi	Battery Chemistry Lithium-Ion