

2016 Toyota Prius 5dr HB Three Touring (Natl)

JTDKARFUXG3012136 • 206,472mi

Front Wheel Drive • 1.8L 4 Cylinder Engine • Gas/Elec (1.3 kWh) • CVT Transmission • Hard Top • Leather

Lane/Run 4/64 Facilitation Manheim California Seller LARRY H MILLER TOYOTA LEMON GROVE



Condition Details



Drivable



No Structural Damage



Starts



Prior Paint



No Odor



Tires



Keys

Fobs

2

0



AutoCheck Clean



Title? (No Data)



Announcements

- AS IS NO ARB

High Value Options

- Adaptive Cruise Control
- Back-Up Camera
- Bluetooth Connection
- Climate Control
- Fog Lamps
- Hard Disk Drive Media Storage
- Keyless Start
- Lane Departure Warning
- Lane Keeping Assist
- Navigation System
- Satellite Radio
- Smart Device Integration
- Tire Pressure Monitor

Condition Details












None ● ● ● Severe


● Structural Issue

Exterior (14)

Description	Condition	Status	Image	Additional Info
● Windshield	Star in Glass			
● Front Bumper Cover	Misaligned			

Description	Condition	Status	Image	Additional Info
● Hood	Heavy Mult Scratches			
● LF Fender	Mult Dents/Paint Dmg			
● L Headlight	Faded			
● L Qtr Panel Molding	Peeling			
● LR Door	Mult Dents/Paint Dmg			
● LR Wheel	Curb Rash			
● Rear Bumper Cover	Prev Repair			
● RR Door	Mult Dents/Paint Dmg			
● R Headlight	Faded			
● R Qtr Panel	Mult Dents/Paint Dmg			
● R Qtr Panel Molding	Peeling			
● RF Wheel	Curb Rash			

Interior (1)

Description	Condition	Status	Image	Additional Info
● Steering Wheel	Worn			

Structure (0)

No structural condition items were reported


Other (1)

Description	Condition Severity	Status	Image	Additional Info
-------------	--------------------	--------	-------	-----------------

● Engine Noise

Tires & Wheels

Wheels Aluminum



Left Front
Other
6/32"
215/45R17

Right Front
Other
6/32"
215/45R17

Left Rear
Other
5/32"
215/45R17

Right Rear
Other
7/32"
215/45R17

Spare
(Compact)
N/A

● 6/32 +
● 5/32 to 4/32
● < 4/32
● N/A

History



No. of Historical Events 16
Last Reported Event Date 08/28/2023
Calculated Owners 2
Last Reported Mileage 206,472
Calculated Accidents 0

Title and Problem Check ✔ Vehicle checks out!
Odometer Check ✔ Vehicle checks out!
Use and Event Check ! Vehicle Use or Event information available
AutoCheck Buyback Protection ✔ Qualifies

CARFAX

[View CARFAX](#)

Details

Exterior Color Gray	MSRP --	Received Date 08/25/2023	In Service Date --	Org Mfg Basic Warranty *3 Years/36,000 Miles
Interior Color Black	Title State --	Inspection Location Manheim California		*Manheim is not responsible for voided warranties
Top Type Hard Top	Title Received --	Work Order 3474727		

EV Information

Current Range --	Battery Health Score --	Charging Cable Not Applicable	Charging Level --	Battery Warranty 8 Years/100000 mi
State of Charge --	Connector Type --	Battery Capacity 1.3 kWh	EPA Mileage --	Battery Chemistry Nickel-Metal Hydride